

Fig. 2






Fig. 3



<u>noosessessesses</u>

Fig. 4

Slipping torque Measurement temperature: RT



O: Present Invention Products (Examples)

△: Conventional press-fitting type (Comparative Examples)